



Utah!

Where ideas connect

Department of Environmental Quality
Division of Water Quality

Michael O. Leavitt
Governor

Dianne R. Nielson, Ph.D.
Executive Director

Don A. Ostler, P.E.
Director

288 North 1460 West
P.O. Box 144870
Salt Lake City, Utah 84114-4870
(801) 538-6146
(801) 538-6016 Fax
(801) 536-4414 T.D.D.
www.deq.utah.gov

Water Quality Board

K.C. Shaw, P.E.

Chairman

William R. Williams

Vice-Chairman

Robert G. Adams

Nan Bunker

Ray M. Child, C.P.A.

Neil K. Kochenour, M.D.

Dianne R. Nielson, Ph.D.

Ronald Sims, Ph.D.

Douglas E. Thompson, Mayor

J. Ann Wechsler

Don A. Ostler, P.E.

Executive Secretary

October 28, 2002

Mr. Mike Glasson, Senior Geologist
Andalex Resources, Inc.
Centennial Project
P. O. Box 902
Price, Utah 84501

FAXED OK
Jacobs
10/27/02

Dear Mike:

Subject: Reconnaissance Inspection at Andalex Resources, Inc. Centennial Project

On September 18, 2002, I completed a Reconnaissance Inspection of the Centennial Mine site. Two subjects were discussed that should be addressed in this letter. First, general storm water permitting, was discussed. If you have any questions regarding the necessity of obtaining a general storm water permit or how to do so please contact Tom Rushing of the Division of Water Quality at (801) 538-6146. Second, you indicated that Andalex might have a mine water discharge for a couple of months starting in November. I want to take this opportunity to remind Andalex to obtain a whole effluent toxicity analysis of the mine water discharge.

During this inspection no deficiencies were noted. Please give me a call if you have any questions (801) 538-6058.

Sincerely,

Michael D. Herkimer, Environmental Scientist
Permits and Compliance Section

MDH:st

Enclosure

cc: Donna Inman, EPA Region VIII, (w/encl)
Claron Bjork, Southeastern Utah District Health Dept., (w/encl)
David Ariotti, District Engineer, (w/encl)
Pam Grubaugh Littig, DOGM, (w/encl)
Wq\permits\mherkimer\wp\andelixins.ltr

RECEIVED

OCT 30 2002

DIV. OF OIL, GAS & MINING

Section A: National Data System Coding

[illegible]



| | | | |
|--|--|------------------------------|-----------------------------------|
| Name and Location of Facility Inspected ANDALEX RESOURCES – CENTENNIAL PRLECT | | Entry Time 10:30 A.M. | Permit Effective Date 8/1/98 |
| | | Exit Time/Date | Permit Expiration Date 4/30/03 |
| Name(s) of On-Site Representative(s) MIKE GLASSON | | Title(s) SENIOR GEOLOGIST | Phone No(s) (435) 637-5385 |
| Name, Address of Responsible Official LANE ADAIR | | Title GENERAL MANAGER | |
| | | Phone No. (435) 564-4000 | Contacted NO |

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

| | | | | | | | |
|---|----------------------|---|--------------------------|---|-------------------------|---|--------------------------|
| S | Permit | S | Flow Measurement | N | Pretreatment | S | Operations & Maintenance |
| S | Records/Reports | S | Laboratory | N | Compliance Schedules | N | Sludge Disposal |
| S | Facility Site Review | S | Effluent/Receiving Water | S | Self-Monitoring Program | | Other: |

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

FLOW MEASURED WITH BUCKET AND STOP WATCH.
JBR - DOES MONITORING FOR UPDES - CONTRACTED
LAB - CT&E
STORM WATER PERMIT CALL 538-6146 AND SPEAK WITH TOM RUSHING

| | | |
|--|--|----------------------|
| Name(s) And Signature(s) of Inspector(s)  MICHAEL D. HERKIMER | Agency/Office/Telephone DIVISION OF WATER QUALITY | Date 10/27/02 |
| Signature of Reviewer  GAYLE J. SMITH, MANAGER PERMITS & COMPLIANCE | Agency/Office DIVISION OF WATER QUALITY | Date 10/28/02 |

Regulatory Office Use Only

| Regulatory Office Use Only | | |
|----------------------------|------|-------------------|
| Action Taken | Date | Compliance Status |